17. SUGGESTED REPLACEMENT TRANSISTORS

LINE No.	1 TYPE NO. TO BE REPLACED	The Following Type Numbers Are Suggested By The Manufacturer As Their Nearest Replacement To The Type In The Left Column											
		TYPE NO.	MFR.	TYPE NO.	MFR.	TYPE NO.	MFR.	TYPE NO.	MFR.	TYPE NO.	MFR.	TYPE NO.	MFR.
1▼	2SA565	BC327	PHIN										
2▼	2SA566	BC238	PHIN										
3▼	2SA578	BC177	PHIN	BC557	PHIN								
4▼	2SA666	BC549	PHIN										
5▼	2SA671	BC438	PHIN	2SC1061	MEHK								
6▼	2SA672	BC557	PHIN										
7▼	2SA673	BC327	PHIN										
8▼	2SA677	BC328	PHIN										
9▼	2SA678	BC327	PHIN										
10▼	2SA683	BC327	PHIN										
11▼	2SA704	BC328	PHIN										
12▼	2SA705	BC327	PHIN										
13▼	2SA711	2N5583	MOTA										
14▼	2SA715	BC234	PHIN										
15▼	2SA719	BC328	PHIN	2SC1317	MEHK								
16▼	2SB124	BDX96	PHIN										
17▼	2SB125	BDX92	PHIN										
18▼	2SB128	BDX96	PHIN										
19▼	2SB129	BDX96	PHIN										
20▼	2SB140	BDX92	PHIN										
21▼	2SB141	BDX96	PHIN										
22▼	2SB147	BDX96	PHIN										
23▼	2SB148	BDX96	PHIN										
24▼	2SB149	BDX92	PHIN										
25▼	2SB228	BDX96	PHIN										
26▼	2SB229	BDX96	PHIN										
27▼	2SB232	BDX96	PHIN										
28▼	2SB242	BD434	PHIN										
29▼	2SB246	BD434	PHIN										
30▼	2SB247	BD434	PHIN										
31▼	2SB249	BDX96	PHIN										
32▼	2SB252A	BDX96	PHIN										
33▼	2SB253	BDX96	PHIN										
34▼	2SB282	BDX96	PHIN										
35▼	2SB283	BDX92	PHIN										
36▼	2SB284	BDX92	PHIN										
37▼	2SB285	BDX96	PHIN										
38▼	2SB303	BC179	PHIN	BC559	PHIN								
39▼	2SB337	BDX92	PHIN										
40▼	2SB339	BDX96	PHIN										
41▼	2SB340	BDX96	PHIN										
42▼	2SB341	BDX96	PHIN										
43▼	2SB367	BD434	PHIN										
44▼	2SB368	BD434	PHIN										
45▼	2SB382	BC179	PHIN	BC559	PHIN								
46▼	2SB383	BC179	PHIN	BC559	PHIN								
47▼	2SB424	BDX96	PHIN										
48▼	2SB425	BDX96	PHIN										
49▼	2SB426	BDX92	PHIN										
50▼	2SB462	BDX96	PHIN										
51▼	2SB465	BDX96	PHIN										
52▼	2SB471	BDX92	PHIN										
53▼	2SB472	BDX96	PHIN										
54▼	2SB473	B434	PHIN										
55▼	2SB481	BD434	PHIN										
56▼	2SB492	BD434	PHIN										
57▼	2SB493	BDX92	PHIN										
58▼	2SC635	2N3632	MOTA										
59▼	2SC636	2N3632	MOTA										
60▼	2SC651	2N4428	MOTA										
61▼	2SC652	MRF515	MOTA										
62▼	2SC823	2N5943	MOTA										
63▼	2SC824	2N5943	MOTA										
64▼	2SC831	2N3927	MOTA										
65▼	2SC852	2N5943	MOTA										
66▼	2SC890	MRF515	MOTA										
67▼	2SC988A	MRF904	MOTA										
68▼	2SC990	2N5646	MOTA										
69▼	2SC1090	BFR90	MOTA										
70▼	2SC1119	MRF902	MOTA										
71▼	2SC1251	MRF511	MOTA										
72▼	2SC1259	2N6083	MOTA										
73▼	2SC1297	2N6082	MOTA										
74▼	2SC1298	2N6084	MOTA										
75▼	2SC1306	MJE1909	MOTA	PTC186	MAL								
76▼	2SC1329	MRF234	MOTA										
77▼	2SC1336	MRF902	MOTA										
78▼	2SC1347	BC337	PHIN	2SA731									
79▼	2SC1359	BF494	PHIN										
80▼	2SC1360	BF199	PHIN										
81▼	2SC1365	MRF517	MOTA										
82▼	2SC1366	MRF517	MOTA										
83▼	2SC1398	BD235	PHIN										
84▼	2SC1606	MRF327	MOTA	PTC143	MAL								
85▼	2SC1678	MJE1909	MOTA	PTC185	MAL								
86▼	2SC1804	MRF321	MOTA										
87▼	2SC1805	MRF323	MOTA										
88▼	2SC1806	MRF5177A	MOTA										
89▼	2SC1807	BFY90	MOTA										
90▼	2SC1808	2N5944	MOTA										
91▼	2SC1816	MJE1909	MOTA										
92▼	2SC1946	MRF222	MOTA										
93▼	2SC1947	2N3924	MOTA										
94▼	2SC1949	MRF962	MOTA										
95▼	2SC1966	2N5944	MOTA										
96▼	2SC1967	2N5945	MOTA										
97▼	2SC1968	MRF641	MOTA										
98▼	2SC2078	MJE1909	MOTA										
99▼	2SC2092	MJE1909	MOTA										
100▼	2SC2132	MRF646	MOTA										
101▼	2SC2166	MJE1909	MOTA										
102▼	2SC2358	MJ12010	MOTA										
103▼	2SC2359	MJ4381	MOTA										
104▼	2SC2366	MJ10016	MOTA										
105▼	2SC2371	MJE3439	MOTA										
106▼	2SC2373	MJE13006	MOTA										
107▼	2SC2388	2N6543	MOTA										
108▼	2SC2397	MJE3055T	MOTA										
109▼	2SC2402	2N6546	MOTA										
110▼	2SC2403	MJ10015	MOTA										

Datasheet.Company