

17. SUGGESTED REPLACEMENT TRANSISTORS

1		The Following Type Numbers Are Suggested By The Manufacturer As Their Nearest Replacement To The Type In The Left Column											
LINE No.	TYPE NO. TO BE REPLACED	TYPE NO.	MFR.	TYPE NO.	MFR.	TYPE NO.	MFR.	TYPE NO.	MFR.	TYPE NO.	MFR.	TYPE NO.	MFR.
1▼	TIP147A	BDX66BB	PHIN										
2▼	TIP150	MJE13006	MOTA										
3▼	TIP151	MJE13007	MOTA										
4▼	TIP152	MJE13007	MOTA										
5▼	TIP160	MJ10002	MOTA										
6▼	TIP161	MJ10002	MOTA										
7▼	TIP162	MJ10012	MOTA										
8▼	TIP303	2N6544	MOTA										
9▼	TIP304	2N6544	MOTA										
10▼	TIP305	2N6545	MOTA										
11▼	TIP306	2N6545	MOTA										
12▼	TIP309	BU208	MOTA										
13▼	TIP310	BU208	MOTA										
14▼	TIP531	2N6546	MOTA	2N6576	TRWS								
15▼	TIP532	2N6547	MOTA	2N6577	TRWS								
16▼	TIP536	BUX80	PHIN										
17▼	TIP537	BUX80	PHIN										
18▼	TIP550	BU205	MOTA	PTC129A	MAL								
19▼	TIP551	BU205	MOTA	PTC129A	MAL								
20▼	TIP552	BU207	MOTA	PTC129A	MAL								
21▼	TIP553	BU208	MOTA	PTC146	MAL								
22▼	TIP554	2N6306	MOTA	BUX82	PHIN	PTC129A	MAL						
23▼	TIP555	BUX82	PHIN										
24▼	TIP556	BUX82	PHIN										
25▼	TIP558	BUX80	PHIN										
26▼	TIP559	BUX80	PHIN										
27▼	TIP560	BUX80	PHIN										
28▼	TIP561	BUX80	PHIN										
29▼	TIP562	2N6546	MOTA	BUX80	PHIN								
30▼	TIP563	2N6547	MOTA	BUX80	PHIN								
31▼	TIP575	BUX82	PHIN	SVT7523	TRWS								
32▼	TIP575A	BUX82	PHIN	SVT7520	TRWS								
33▼	TIP575B	BUX82	PHIN	SVT7524	TRWS								
34▼	TIP575C	BUX82	PHIN	SVT7525	TRWS								
35▼	TIP620	BUX63	PHIN										
36▼	TIP621	BUX63A	PHIN										
37▼	TIP2955	MJE2955	MOTA										
38▼	TIP3055	MJE3055	MOTA										
39▼	V996	MRF902	MOTA										
40▼	WT5100	MJ13015	MOTA										
41▼	WT5200	2N6547	MOTA										
42▼	ZTX311	BSX19	PHIN										
43▼	ZTX342	BSS38	PHIN										
44▼	ZTX500	BC3287	PHIN										
45▼	ZTX501	BC327	PHIN										
46▼	ZTX502	BC327	PHIN										
47▼	ZTX503	BC327	PHIN										

Datasheet.Company