

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
<b>2N3734</b> (Cont'd) 2N5337 3 MOTA D42C8 3 GESY	<b>2N3742</b> (Cont'd) THC3742 1 SPR D44T4 3 GESY DE996 3 DGE	<b>2N3767</b> (Cont'd) D42T1 3 GESY D44C6 3 GESY D44C8 3 GESY DE384 3 DGE MJE182 3 NSC SD339 3 MIKG ST44C11 3 STI	<b>2N3788</b> (Cont'd) SVT7523 3 TRWS	<b>2N3788A</b> (Cont'd) TMPT3798A 1 SPR TP3798A 1 SPR 2N2905A 3 PHIN DE159 3 DGE GES6017 3 GESY THC3798 3 SPR TMPT3798 3 SPR TP3798 3 SPR	<b>2N3808</b> (Cont'd) MP351-78 1 MPS IT132 3 INL MP310 3 MPS MP351-52 3 MPS MP352-78 3 MPS
<b>2N3735</b> 2N4305 1 TRWS BSX59 1 PHIN D40D7 1 GESY 2N5321 3 RCA 2N5337 3 MOTA BSX32 3 SGSI D40D4 3 GESY	<b>2N3743</b> 2N5416 1 RCA BFT19B 1 RCA DE154 1 DGE GES3743 1 GESY THC3743 1 SPR DE397 3 DGE	<b>2N3768</b> SFN350 1 SOD	<b>2N3789</b> 2N3791 1 RCA BDV92 1 PHIN D44H7 1 GESY DE219 1 DGE 2N6246 3 RCA 2N6254 3 RCA 2N6292 3 RCA 2N6469 3 RCA BDV94 3 PHIN BDX92 3 PHIN BUV26 3 APX D44H8 3 GESY D45C2 3 GESY D45C5 3 GESY D45C6 3 GESY D45VH7 3 GESY ST44H7 3 STI	<b>2N3799</b> DE159 1 DGE GES6017 1 GESY THC3799 1 SPR TP3799 1 SPR BFX37 3 SGSI THC3799A 3 SPR TP3799A 3 SPR	<b>2N3809</b> 2N3811A 1 MOTA IT122 1 INL MP351-78 1 MPS IT132 3 INL MP310 3 MPS MP352-78 3 MPS
<b>2N3736</b> D40D1 1 GESY	<b>2N3744</b> D44C5 1 GESY 2N6290 3 RCA BD239 3 RCA BU407 3 APX ST44C5 3 STI	<b>2N3771</b> DE181 1 DGE 2N4311 3 TRWS	<b>2N3790</b> 2N3792 1 RCA BDV94 1 PHIN D44H10 1 GESY DE219 1 DGE 2N6247 3 RCA 2N6292 3 RCA BDX94 3 PHIN BUV26 3 APX D44H11 3 GESY D45VH10 3 GESY ST44H10 3 STI	<b>2N3799A</b> 2N3799 1 MOTA THC3799A 1 SPR TP3799A 1 SPR DE159 3 DGE GES6017 3 GESY THC3799 3 SPR TP3799 3 SPR	<b>2N3810</b> DE82 1 DGE MD1123 1 MOTA MP352-78 1 MPS IT130 3 INL IT139 3 INL MP351-52 3 MPS
<b>2N3737</b> D40D7 1 GESY DE123A 3 DGE	<b>2N3745</b> D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	<b>2N3772</b> DE284 1 DGE	<b>2N3791</b> BDV94 1 PHIN D44H8 1 GESY DE219 1 DGE 2N4904 3 RCA 2N4905 3 RCA 2N6246 3 RCA 2N6292 3 RCA BDV92 3 PHIN BDX92 3 PHIN BUV26 3 APX D44H7 3 GESY D45C6 3 GESY D45C8 3 GESY ST44H8 3 STI	<b>2N3800</b> 2N3806 1 MOTA DE82 1 DGE IT132 1 INL MP351-52 1 MPS 2N3811A 3 MOTA IT122 3 INL MP351 3 MPS MP351-78 3 MPS	<b>2N3811</b> DE82 1 DGE MD1123 1 MOTA MP352-78 1 MPS IT130 3 INL IT139 3 INL MP351-52 3 MPS
<b>2N3738</b> 2N3584 1 RCA D42T1 1 GESY DE124 1 DGE 2N3583 3 RCA BU133 3 PHIN BUX67A 3 RCA BUX67B 3 RCA D40V1 3 GESY D44T1 3 GESY D44T2 3 GESY DE286 3 DGE	<b>2N3746</b> D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	<b>2N3773</b> DE284 1 DGE SDT7734 1 SOD SDT7735 1 SOD SDT9702 1 SOD SDT9703 1 SOD SDT9705 1 SOD SDT9706 1 SOD SDT9804 1 SOD 2N4348 3 RCA 2N5629 3 MOTA 2N5630 3 MOTA	<b>2N3792</b> BDV94 1 PHIN D44H10 1 GESY DE219 1 DGE 2N6247 3 RCA 2N6292 3 RCA BDX94 3 PHIN BUV26 3 APX D44H11 3 GESY D45VH10 3 GESY ST44H10 3 STI	<b>2N3801</b> 2N3807 1 MOTA DE82 1 DGE IT132 1 INL MP351-78 3 MPS	<b>2N3812</b> IT132 1 INL MP351-78 1 MPS MP351 3 MPS
<b>2N3739</b> 2N3585 1 RCA D42T2 1 GESY DE124 1 DGE 2N3584 3 RCA 2N4240 3 GSE BU126 3 PHIN BUX67B 3 RCA BUX67C 3 RCA D40V1 3 GESY D40V3 3 GESY D40V4 3 GESY D44T2 3 GESY D44T3 3 GESY D44T4 3 GESY DE286 3 DGE	<b>2N3747</b> D44C6 1 GESY 2N6290 3 RCA BD239 3 RCA BU407 3 APX ST44C6 3 STI	<b>2N3774</b> 2N4234 1 MOTA 2N5783 1 RCA DE129 1 DGE BSS44 3 SGSI D41E1 3 GESY D42C7 3 GESY SDT3552 3 SOD	<b>2N3793</b> BC107 1 SGSI BC337 1 PHIN DE199 1 DGE THC3793 1 SPR BC377 3 SGSI BCX19 3 PHIN BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR THBC337 3 SPR	<b>2N3802</b> 2N3808 1 MOTA DE82 1 DGE IT132 1 INL MP351-52 1 MPS 2N3811A 3 MOTA IT122 3 INL MP351 3 MPS MP351-78 3 MPS	<b>2N3813</b> IT132 1 INL MP351-78 1 MPS MP351 3 MPS
<b>2N3740</b> 2N5955 1 RCA D45C7 1 GESY DE218 1 DGE 2N6107 3 RCA 2N6317 3 MOTA BD240A 3 RCA SDT3576 3 SOD SDT3702 3 SOD SDT3704 3 SOD SDT3707 3 SOD SDT3708 3 SOD SDT3710 3 SOD SDT3711 3 SOD SDT3713 3 SOD SDT3716 3 SOD SDT3722 3 SOD SDT3727 3 SOD SDT3730 3 SOD ST45C7 3 STI	<b>2N3748</b> D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	<b>2N3775</b> 2N4235 1 MOTA 2N5781 1 RCA DE129 1 DGE 2N5782 3 RCA BSS44 3 SGSI D41E5 3 GESY SDT3550 3 SOD SDT3553 3 SOD	<b>2N3794</b> BC108 1 SGSI BC337 1 PHIN DE199 1 DGE THC3794 1 SPR BC377 3 SGSI BCX19 3 PHIN BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC108 3 SPR THBC337 3 SPR	<b>2N3803</b> 2N3809 1 MOTA IT132 1 INL 2N3811A 3 MOTA IT122 3 INL MP351 3 MPS MP351-78 3 MPS	<b>2N3814</b> IT132 1 INL MP351-78 1 MPS MP351 3 MPS
<b>2N3741</b> 2N5954 1 RCA BD140 1 PHIN D45C10 1 GESY DE218 1 DGE 2N4920 3 MOTA 2N6107 3 RCA 2N6318 3 MOTA BD240B 3 RCA MJE172 3 NSC SD340 3 MIKG SDT3577 3 SOD SDT3705 3 SOD SDT3714 3 SOD SDT3718 3 SOD SDT3723 3 SOD SDT3728 3 SOD SDT3731 3 SOD ST45C10 3 STI	<b>2N3749</b> D43C6 1 GESY 2N6109 3 RCA D41D4 3 GESY DE128 3 DGE MDS77 3 MOTA THC3120 3 SPR	<b>2N3776</b> 2N5322 1 SGSI 2N5679 1 MOTA DE323 1 DGE D42C8 3 GESY DE129 3 DGE	<b>2N3795</b> BC337 1 PHIN DE199 1 DGE THC3793 1 SPR BC377 3 SGSI BCX19 3 PHIN BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR THBC337 3 SPR	<b>2N3804</b> 2N3810 1 MOTA IT130 1 INL MP351-52 1 MPS DE82 3 DGE MP351-78 3 MPS MP352 3 MPS	<b>2N3815</b> IT132 1 INL MP351-78 1 MPS MP351 3 MPS
<b>2N3742</b> 2N3439 1 RCA DE154 1 DGE GES3742 1 GESY	<b>2N3750</b> D43C8 1 GESY 2N6107 3 RCA D40D1 3 GESY DE106 3 DGE MDS77 3 MOTA THC3072 3 SPR	<b>2N3777</b> 2N5322 1 SGSI 2N5679 1 MOTA DE323 1 DGE D42C8 3 GESY DE129 3 DGE	<b>2N3796</b> DE462 1 DGE	<b>2N3805</b> 2N3811 1 MOTA IT130 1 INL MP351-52 1 MPS DE82 3 DGE MD1123 3 MOTA MP352 3 MPS MP352-78 3 MPS	<b>2N3816</b> IT130 1 INL IT130A 3 INL MP352 3 MPS MP352-78 3 MPS
	<b>2N3751</b> D44C8 1 GESY 2N3054 3 RCA 2N3878 3 RCA 2N3879 3 RCA 2N4923 3 MOTA 2N6292 3 RCA 2N6315 3 MOTA BD235 3 PHIN BD239A 3 RCA BU407 3 APX D40V1 3 GESY D42C2 3 GESY D42C5 3 GESY D42C6 3 GESY D42C8 3 GESY D44C2 3 GESY D44C3 3 GESY D44C4 3 GESY D44C5 3 GESY D44C7 3 GESY MJE182 3 NSC SD339 3 MIKG ST44C8 3 STI	<b>2N3778</b> 2N5679 1 MOTA DE323 3 DGE	<b>2N3797</b> DE462 1 DGE	<b>2N3806</b> 2N3811A 1 MOTA DE82 1 DGE IT122 1 INL MP351-78 1 MPS IT132 3 INL IT139 3 INL MP310 3 MPS MP351-52 3 MPS MP352-78 3 MPS	<b>2N3817</b> IT130 1 INL IT130A 1 INL MP352 3 MPS MP352-78 3 MPS
	<b>2N3752</b> D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	<b>2N3779</b> 2N4234 1 MOTA 2N5781 1 RCA DE129 1 DGE BSS44 3 SGSI D41E1 3 GESY D42C7 3 GESY SDT3550 3 SOD SDT3553 3 SOD	<b>2N3798</b> 2N2905A 1 PHIN DE159 1 DGE GES6017 1 GESY THC3798 1 SPR TMPT3798 1 SPR TP3798 1 SPR THC2905A 3 SPR THC3798A 3 SPR TN2905A 3 NSC TP2905A 3 SPR TP3798A 3 SPR	<b>2N3807</b> 2N3811A 1 MOTA IT122 1 INL DE82 3 DGE IT132 3 INL IT139 3 INL MP310 3 MPS MP351-52 3 MPS MP352-78 3 MPS	<b>2N3818</b> 2N5484 1 INL BF245C 1 PHIN MPP108 1 MOTA THJ3819 1 SPR TMPF3819 1 SPR 2N4224 3 INL 2N4416 3 INL 2N5246 3 IFC 2N5458 3 INL 2N5486 3 MOTA 2N5953 3 IFC DE180 3 DGE THJ5484 3 SPR TMPF5484 3 SPR
	<b>2N3753</b> D44C8 1 GESY 2N6292 3 RCA BD239A 3 RCA BU407 3 APX ST44C8 3 STI	<b>2N3780</b> 2N4236 1 MOTA 2N5321 1 SGSI 2N5781 3 RCA D41E7 3 GESY D42C7 3 GESY DE128 3 DGE DE129 3 DGE	<b>2N3799</b> 2N2905A 1 PHIN DE159 1 DGE GES6017 1 GESY THC3798 1 SPR TMPT3798 1 SPR TP3798 1 SPR THC2905A 3 SPR THC3798A 3 SPR TN2905A 3 NSC TP2905A 3 SPR TP3798A 3 SPR	<b>2N3808</b> 2N3811A 1 MOTA IT122 1 INL DE82 3 DGE IT132 3 INL IT139 3 INL MP310 3 MPS MP351-52 3 MPS MP352-78 3 MPS	<b>2N3819-18</b> 2N5484 3 INL <b>2N3820</b> 2N2608 1 INL DE326 1 DGE J270 1 SIX MPP161 1 MOTA THJ3820 1 SPR TMPF3820 1 SPR TP3820 1 SPR